Immoustant	Catatu	Dullatia	Even	COLOUD	
Important	Salety	Dulletill	LIOIII	Soland	



To:	PLATT ELECTRIC-WHSE 75 cc:					
From:	Ray Dubiel					
Date	19-Sep-2008					
Subject:	Important Safety Bulletin from SolaHD on P/N# SDN20-24-100P					

Dear SolaHD Customer,

We have discovered that a number of SolaHD SDN20-24-100P power supply units with date codes of MG020400000 through MG350899999 may have been manufactured with an input relay that does not conform with all the intended applications for the supply. There is no effect on reliability or safety when the power supply is used in an ordinary location. However, units with the non-conforming relay have not been tested to UL60079-15 safety standard for use in Class 1, Zone 2 locations. Although we have had no reported incidents involving the product in the years these have been in service, **failure to replace this power supply in a hazardous Class 1 Zone 2 location could result in fire or explosion**. Therefore, we feel the safest course of action would be to replace them for customers who do use them in those locations.

Our records indicate that you have purchased the following quantities of SolaHD P/N# SDN20-24-100P during the time frame identified (see the attached for quantities, shipment dates and Purchase Order Numbers). If you have any affected inventory in stock at your location, we request that you contact us for an RMA and return your stock to us for inspection. We also ask that you pass this notice on to your customers. Alternately, you may wish to provide us with the names and addresses of your customers along with any information that would help us identify the power supplies to your customers, and we will contact them for you. This information will only be used for the purposes of this bulletin.

Where units are in service in a Class 1, Zone 2 area, we will replace them at no charge. We will send the replacements to the customer and they can swap the old unit out for the new so there is no extended down time.

Please contact Becky Smith to arrange all returns and replacements associated with this issue. Becky can be reached by calling 800-377-4384 and taking option 3 on the menu or by fax at 256-638-9775.

If you have any questions, please contact me at 847-268-6619, e-mail me at ray.dubiel@emerson.com, or fax them to me at 847-268-6033.

Please accept our apologies for any inconvenience that may have been caused.

Regards,

Ray Dubiel Director of Engineering, SolaHD

Important	Safety	Bulletin	From	SolaHD	
-----------	--------	----------	------	--------	--